NEW CONTACTS FOR CONNECTOR N | 1/1 | 2

OUR REF.NO 040

1. CAUSE : Contact B,C, and D : Weakened.

2. MODIFICATION : Material of contact B,C, and D : Changed.

3. MODIFICATION DATE : Since 1987 March production.

New P/No. 6284 86562 Contact D
6284 86582 Contact B
6284 86572 Contact C



Remarks

24 FEB 87

NEW RELEASE PLATE FOR AUTO BELLOWS 1/2

OUR REF.NO. 021

1. CAUSE : Release plate(type 1) does not push the release button of body.

2. MODIFICATION : Shape of release plate.

3. MODIFICATION DATE : From October, 1986.

4. REPAIR STEP : Replacement of release plate (type 2)



Remarks

MOUNTING RING ASS'Y FOR M645 SUPER (AUTO BELLOWS) 2/2

OUR REF.NO. 021



Remarks